

1/28





FIG.1

FIG. 1 is a schematic diagram of a glass powder production process.

2/28



3/28




FIG.3

4/28




FIG. 4




FIG. 5

5/28




FIG. 6




FIG. 7

410338-0997-122101

6/28




FIG. 8

7/28




FIG.9




FIG.10

8/28




FIG.11

41890-01616-136104



9/28




FIG.12

10/28




FIG. 13




FIG. 14

FIG. 13

11/28




FIG. 15




FIG. 16

12/28




FIG.17

13/28




FIG. 18




FIG. 19

14/28




FIG.20




FIG.21

FIG. 20




FIG.22

"Patent" Secret

16/28




FIG.23



17/28




FIG.24

FIG. 24

18/28




FIG.25

19/28




FIG. 26




FIG. 27

20/28




FIG.28

FIG. 28 is a flowchart of the process.

21/28




FIG.29




FIG.30




FIG.31

FIG. 29

22/28




FIG.32

FIG. 32 is a schematic diagram of a glass powder processing apparatus.




FIG.33

24/28




FIG.34

"Not Yet Assigned"



25/28




FIG. 35A




FIG. 35B




FIG. 35C




FIG. 35D




FIG. 35E




FIG. 35F

26/28




FIG.36

27/28




FIG.37

FIG. 37 " 27/28 " 27/28

28/28




FIG.38